UNITED STATES DEPARTMENT OF COMMERCE Patent and Trademark Office ASSISTANT SECRETARY OF COMMERCE AND COMMISSIONER OF PATENTS AND TRADEMARKS

P.O. Box 1450 Alexandria, VA 22313-1450

August 26, 2008

WENDEROTH, LIND & PONACK L.L.P. 2033 K. STREET, NW SUITE 800

WASHINGTON DC 20006

Patent No.

: 7,296,982 B2

Inventor(s)

: Atsushi Sakuda, et al.

Issued

: November 20, 2007

For

AN AIR SUPPLY DEVICE HAVING SEALANT ATTACHED TO BOTH SIDES OF ROLLING

ELEMENTS OF BEARING SUPPORTING AN

ORBITAL SCROLL

Doc. No.

2005 1981A

To Whom It May Concern:

The Certificate of Correction issued on <u>August 19, 2008</u>, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

In the issued certificate of correction, the correction to change the title should have also been listed to be incorporated at Column 1, line 1. A superseding cofc will be issued to include the change of the title to occur at Column 1, line 1.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson (703) 308-9390 ext. 111 For Mary F. Diggs, Supervisor Decisions & Certificates of Correction Branch (703) 305-8309 / 703-308-9390 ext. 125